ROOSEVELT IRRIGATION DISTRICT

WELL DATA

Report on 12E-10N

Work started - July 2, 1951
Work completed - August 17, 1951

Total Depth - 800'

Depth of Casing - 800! - 20"

Log of Well

01 - 21 Top soil

2' - 6' Silt sand gravel and boulders

61 - 81 Hard clay

8' - 20' Sand gravel and boulders

201 - 71: Clay and boulders

71' - 201' Sandy clay and gravel

201' - 340' Sticky Clay and gravel

340' - 525' Sandy clay and gravel

525' - 582' Sandy clay

582' - 592' Sand

592' - 625' Sandy clay

625' - 716' Sticky clay

716' - 800' Hard sticky clay

Perforations

Perforated from 160' to 780'
Perforations 5/8" X 4" - 10 holes per 12"

Depth at which water was first found - 125'

Standing level before perforating - 125'

Standing level after perforating - 125

Remarks

J. O. Evans, Driller for Roscoe Moss Company

COST

Drilling and casing 20" No. 10 gauge well 800' - \$9,895.00



16825 S. Weber Drive, Chandler, AZ 85226-4112 * 480-961-1141 * Fax 480-961-0290 18403 W. McDowell Road, Goodyear, AZ 85338-5613 * 623-853-9901 * Fax 623-853-9902 2838 W. Ruthrauff Road, Tucson, AZ 85705-1860 * 520-887-2170 * Fax 520-408-0832

Date: 2-18-08 Roosevelt Irrigation District Job #: 7321 Customer: I-10 west to loop 101 north to Camelback exit west to 107th ave north to end of pavement follow Location: Dirt road along canal well is on left hand side. Well #: 65 1 ½E - 10N Glendale County: Maricopa State: Arizona City: Liner Size: N/A Case Size: 20" ID Drilling Orig. Current 701' S.W.L. 104' Depth 800' Depth Method Reference by: Fred T. P. O. #: Type of Perforation: Mills Knife 159' to 701'. Type Drive Elec. Turbine Results: There is a trace of oil on top of the water. The water was dirty from 104' to 150'. There was heavy build up on the casing from 104' to 300', extra heavy buildup from 300' to 350' & extremely heavy build up from 350' to 701'. The perforations appeared to be partially open to mostly open from 159' to 300', partially open to mostly plugged from 300' to 430' & mostly plugged from 430' to 701'. There was water movement at 159'. There is a lot of corrosion in the casing and large pieces of casing missing from-150' to 170'. There is a hole in the casing at 162'. Could not see the bowls they are possibly under the fill. GPS Elev. 1043' N 33* 31' 20.7" W 112* 16' 57.3" Bottom 800' C:\Documents and Settings\Marianne\My Documents\well reports\RIDwell65.doc